₽				9.4						- T
		UTAH OIL	AND GAS	CONSERV	ATION CO	MMISSIO	N ·			
REMARKS:	*NID CANC	ELLED	9-4-5	7						
and a second				,						
* Was new	is approved									
	11				1. N. 19					
	. :				12 (2 to 10 to	No. 100				
							•			
									·	-
DATE FILED	8-30-5 7							,	Na v-1 4-	-20-
LAND: FEE & PATE		SE NO.		PUBLIC	LEASE NO.			INDIAN	603-24	
DRILLING APPROVED	: *9-4-57									
SPUDDED IN:		1								
COMPLETED:							-			
INITIAL PRODUCTION	1:	1			•			:		
GRAVITY A. P. I.										
GOR:		7				1				
PRODUCING ZONES:		7	-		Charles and					
TOTAL DEPTH:		/								
WELL ELEVATION:	4655 GR V						·		,	-
DATE ABANDONED:	* ZA	0186		L-+						
FIELD OR DISTRICT:	Ratherfor	a 17/1/2	Juanten (Ineth	10					
COUNTY:	San Juan	1/orth	Deser	+ Gree	\mathcal{K}		1			
WELL NO.	. DATEMENTOR	D 41-12	,	AK	1 43	-03	2-110	60		

WELL NO.

LOCATION: 656 FT. FROM (N) CO LINE, 660

TWP. RGE. SEC. OPERATOR

O41 S 23 E 12 SHELL OIL COMPANY

TWP. RGE. SEC. OPERATOR

TWP. RGE. SEC. OPERATOR

Justin Arilled med men drilled

Form 9-331 b (April 1952)

12

(SUBMIT IN TRIPLICATE)


UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

4	Budget Bureau No. 42-R359,4. Approval expires 12-31-60.			
Indian Agency <u>Na va jo</u>				
R	Allottee Tribal Land			

Lease No. 14-20-603-246

SUNDRY NOTICES AND REPORTS ON WELLS

11. Make production test, establish initial rate. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell Oil Company	SUNDRY NOTICES AN	D REPORTS ON WELLS
NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF. NOTICE OF INTENTION TO REPULL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO FULL OR ALTER CASING. NOTICE OF INTENTION TO BULL OR ALTER CASING. NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO SHOOT ALTER SUBSCIPLE TROPPORT OR ABRODOMENT SUBSCQUENT REPORT OF ALTERNOC ASSING NOTICE OF INTENTION TO SHOOT ALTER CASING NOTICE OF INTENTION TO SARROW ALTER CASING NOTICE OF INTENTION TO SARROW ALTER CASING NOTICE OF INTENTION TO SARROW ALTER CASING NOTICE OF INTENTION TO	NOTICE OF INTENTION TO DRILL	CURCEOUENT DEPORT OF WATER CHUZ OFF
NOTICE OF INTENTION TO TEST WATER SHUT-OFF. NOTICE OF INTENTION TO REDRILL OR REPAIR WELL. NOTICE OF INTENTION TO SHOULD OR ALTER CASING. NOTICE OF INTENTION TO SHOULD OR ALTER CASING. NOTICE OF INTENTION TO PULL OR ALTER CASING. NOTICE OF INTENTION TO ABAMDON WELL. (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) **NOTTH DESERT Creek** Well No. 41-12 is located 656 ft. from No. 41-12 is		
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO ABANDON WELL (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) August 13		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE. NOTICE OF INTENTION TO PULL OR ALTER CASING. NOTTH Desert Creek Well No. 41=12 is located 656.ft. from Notice or other Data) North Desert Creek Vell No. 41=12 is located 656.ft. from Notice or other Data) North Desert Creek San Juan (Geridian) North Desert Creek San Juan (Juan) County or Subdivision) DETAILS OF WORK State names of and expected depths to objective analysabove sea level is £655. ft. (approx. ground) DETAILS OF WORK State names of and expected depths to objective analysabove sizes, weights, and lengths of proposed casings; indicate mudding Jobs, comes in proteins and all other important proposed work) 1. Drill 11" hole to 1200'±. 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5779'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. Wash perforations with 500 gal. mud acid. 10. Make production test, establish initial rate. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell. Oil Company. Address. 101 S. Behrend Farmington, N. M. By Shepard		
NOTICE OF INTENTION TO PULL OR ALTER CASING. NOTICE OF INTENTION TO ABANDON WELL August 13		
(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) August 13 , 19 and North Desert Creek Well No. 41-12 is located 656 ft. from North Desert Creek Well No. 41-12 is located 656 ft. from North Desert Creek Well No. 41-12 is located 656 ft. from North Desert Creek (Isage) North Desert Creek San Juan (State or Territory) The elevation of the derrick floor above sea level is 4655 ft. (approx. ground) DETAILS OF WORK State names of and expected depths to objective sands; show airse, weights, and lengths of proposed casings; indicate mudding jobs, cemer ing points, and all other important proposed work) 1. Drill 11" hole to 1200'±, 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal, mid acid. 11. Make production test, establish initial rate. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company. Shell 0il Company. Address. 101 S. Behrand. By B. W. Shepard		1 1
(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) August 13. ,19 g North Desert Creek Well No. 41-12 is located 656 ft. from Not the description of the descript	·	SUPPLEMENTARY WELL HISTORY.
North Desert Creek Well No. 41=12 is located 656 ft. from [N] line and 660 ft. from [E] line of sec. 12 NE 12 415 23E SLEM (Meridian) North Desert Creek San Juan Ultah (County of Subdivision) (State or Territory) The elevation of the derrick floor above sea level is 4655. ft. (approx. ground) DETAILS OF WORK State names of and expected depths to objective sands; shown sizes, weights, and elengths of proposed casings; indicate mudding jobs, cemer inerpotant proposed weigh. 1. Drill 11" hole to 1200'±. 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/for gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal, mud acid. 11. Make production test, establish initial rate. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell 0il Company. Address 101 S. Behrend Farmington, N. M. By Shepard	NOTICE OF INTENTION TO ABANDON WELL	
North Desert Creek Well No. 41=12 is located 656.ft. from No. 41=12 is located	(INDICATE ABOVE BY CHECK MARK NAT	URE OF REPORT, NOTICE, OR OTHER DATA)
North Desert Creek Well No. 41=12 is located 656.ft. from No. 41=12 is located		August 13 19 57
North Desert Creek San Juan Utah (County or Subdivision) (State or Territory) The elevation of the devrick floor above sea level is 4655 ft. (approx. ground) DETAILS OF WORK State names of and expected depths to objective sands; show aixes, weights, and lengths of proposed casings; indicate mudding jobs, cemer ine points, and all other important proposed work) 1. Drill 11" hole to 1200'±. 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal. mud acid. 11. Make production test, establish initial rate. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell Oil Company. Address 101 S. Behrend Farmington, N. M. By Shepard	North Desert Creek	
North Desert Creek San Juan Utah (County or Subdivision) (State or Territory) The elevation of the devrick floor above sea level is 4655 ft. (approx. ground) DETAILS OF WORK State names of and expected depths to objective sands; show aixes, weights, and lengths of proposed casings; indicate mudding jobs, cemer ine points, and all other important proposed work) 1. Drill 11" hole to 1200'±. 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal. mud acid. 11. Make production test, establish initial rate. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell Oil Company. Address 101 S. Behrend Farmington, N. M. By Shepard	NE 12	23E SIBM ange) (Meridian)
County or Subdivision) (State or Territory) The elevation of the derrick floor above sea level is 4655 ft. (approx. ground) DETAILS OF WORK State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cemer ing points, and all other important proposed work) 1. Drill 11" hole to 1200'±. 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal. mud acid. 11. Make production test, establish initial rate. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell 0il Company. Address 101 S. Behrend Farmington, N. M. By B. W. Shepard		· · · · · · · · · · · · · · · · · · ·
DETAILS OF WORK State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cemer ing points, and all other important proposed work) 1. Drill 11" hole to 1200'±. 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal. mud acid. 11. Make production test, establish initial rate. Lunderstand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell 0il Company. Address 101 S. Behrend Farmington, N. M. By B. W. Shepard.	(Field) (County or S	
1. Drill 11" hole to 1200'±. 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'+. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal. mud acid. 11. Make production test, establish initial rate. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell Oil Company Address 101 S. Behrend Farmington, N. M. By J.	The elevation of the derrick floor-above-sea level	is 4655ft. (approx. ground)
1. Drill 11" hole to 1200'±. 2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal. mud acid. 11. Make production test, establish initial rate. **Iunderstand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. **Company Shell Oil Company** **Address 101 S. Behrend By Shelpand B. W. Shepard	DETAILS	OF WORK
2. Cement 8-5/8" casing at 1200'± (depending on water flow) with 400 sacks poz mix followed by 200 sacks cement. 3. Drill 7-7/8" hole to 5790'±. 4. Cement 5-1/2" casing at 5790'± with 200 sacks cement. 5. Clean out to 5775'±. 6. Perforate four 1/2" holes/foot gross interval 5610'±-5660'±. 7. Wash perforations with 200 gal mud acid and inject 2000 gal XFW acid. 8. Make production test and kill with water. 9. Perforate four 1/2" holes/ft. gross interval 5665'±-5760'±. 10. Wash perforations with 500 gal. mud acid. 11. Make production test, establish initial rate. 1 understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Shell Oil Company Address 101 S. Behrend Farmington, N. M. By Shepard	(State names of and expected depths to objective sands; show sizes, w ing points, and all other	veights, and lengths of proposed casings; indicate mudding jobs, cement- r important proposed work)
I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Address 101 S. Behrend Farmington, N. M. By B. W. Shepard	 Cement 8-5/8" casing at 1200'± (deposite position followed by 200 sacks centered). Drill 7-7/8" hole to 5790'±. Cement 5-1/2" casing at 5790'± with sold sacks centered. Clean out to 5775'±. Perforate four 1/2" holes/foot graph. Wash perforations with 200 gal muther. Make production test and kill with self-self. Perforate four 1/2" holes/ft. graph. Wash perforations with 500 gal. muther. 	nent. th 200 sacks cement. coss interval 5610'±-5660'±. ad acid and inject 2000 gal XFW acid. th water. coss interval 5665'±-5760'±. and acid.
Company Shell Oil Company Address 101 S. Behrend Farmington, N. M. By B. W. Shepard	Make production test, establish i	nitial rate.
Address 101 S. Behrend Farmington, N. M. By B. W. Shepard B. W. Shepard	I understand that this plan of work must receive approval in wri	ting by the Geological Survey before operations may be commenced.
Farmington, N. M. By B. W. Shepard	Company Shell Oil Company	
n. oneparu	Address 101 S. Behrend	
Title Exploitation Engineer	Farmington, N. M.	By Bu Shepard B. W. Shepard
		Title Exploitation Engineer



September 4, 1957

Shell 011 Company 101 South Behrend Farmington, New Mexico

Attention: B. W. Shepard

Contlemen:

This is to acknowledge receipt of your notices of intention to drill Well No. North Desert Creek 41-12, 656 feet from the north line and 660 feet from the east line of Section 12, Township 41 South, Range 23 East, and Well No. North Desert Creek 43-12, 1961 feet from the south line and 662 feet from the east line of Section 12, Township 41 South, Range 23 East, SIBM, Sen Juan County, Utah.

Please be advised that approval to drill the above mentioned wells cannot be granted at this time, in view of the fact that they are off of the well location pattern proposed by a pending spacing application filed by the Continental Oil Company on August 30, 1957. (See Rule C-4(a), of our rules and regulations.)

As soon as a date is set for said hearing, you will be notified.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

CLEON B. FRIGHT SECRETARY

CBF:cn

ee: Phil McGrath USGS, Farmington, New Mexico

DR-USGS

May 16, 1958

Shell Oil Company 101 South Behrend Farmington, New Mexico NIP CANCELLER

Re: Well No. RATHERFORD (No. Desert Creek) 41-12, Sec. 12, T. 41 S, R. 23 E, SLEM, San Juan County, Utah

Gentlemen:

This letter is to advise you that the well log for the above mentioned well has not as yet been filed with this office as required by our rules and regulations.

Please complete the enclosed Forms OGCC-3, Log of Oil or Gas Well, in duplicate, and forward them to this office as soon as pecsible.

Yours very truly,

OIL & GAS CONSERVATION COMMISSION

CLEON B. FEIGHT SECRETARY

CBF: on

Encls.



SHELL OIL COMPANY

101 South Behrend Avenue Farmington, New Mexico

May 21, 1958

State of Utah Oil and Gas Conservation Commission Salt Lake City 14, Utah

Gentlemen:

With reference to Mr. Feight's letter of May 16, 1958 regarding a well log on our well No. Ratherford (North Desert Creek) 41-12, we wish to inform you that Shell Oil Company has not drilled a well at this location. We are unable to determine from our records where you may have obtained the impression that such a well exists. If there has been some mistake in well designation perhaps you can clarify the situation for us. We will be glad to cooperate in any way possible.

very truly yours,

R. R. Robison

Division Production Manager

Shell Oil Company 101 South Behrend Farmington, New Mexico

Attention: R. R. Robison, Division

Production Manager

Gentlemen:

This is to acknowledge receipt of your letter of May 21, 1958.

Please be advised that we have checked our records and have found that Well No. Ratherford (North Desert Creek) 41-12, Section 12, T. 41 South, R. 23 East, San Juan County, was never drilled as the location was cancelled.

We hope that our mistake has not inconvenienced you in any way.

Thank you for your cooperation in this matter.

Yours very truly.

OIL & GAS CONSERVATION COMMISSION

CLEON B. FEIGHT SECRETARY

CBF:en